

09632609.080400




FIG. 1

22




FIG. 2




FIG. 3

004080" 6092E960

✓ 120




FIG. 4

98




FIG. 5A

09632609.080400

102




FIG 5B

004080" 6092E960




FIG. 6

004080" 6092E960

✓ 106




FIG. 7

112 ↖




FIG. 8

09632609.080400

004080" 609225960




FIG. 9




FIG. 10



FIG. 11

004080-6092960

004080" 5092E960




FIG. 12A




FIG. 12B

004080"6092E960




FIG. 13A




FIG. 13B

004080" 6092E960

210 E




FIG. 14

210F




FIG. 15

004080" 6092E960

004080-6092E960




FIG. 16

210H.

← 1 Octet →




FIG. 17

09632609.080400

004080" 6092E960

210I




FIG. 18




FIG. 19A




FIG. 19B




FIG. 19C




FIG. 19D




FIG. 20




FIG. 21

004080" 6092E960

311




FIG. 22

400

Frame
Arrival

402

BPC=0; NRC=0
TC=0;
NACKcount=0;
Frm Timer=MaxLife;
Priority=0-3

403

VCS=0
CS=0?

407

In CSS
Interval

409

In PRS
interval

423

In Contention
Window

Transmit segment,
Increment
TC

406

428

ACK
expected?

430

Valid ACK
received?

Resolve
response

424

Contention
Free

426

Interrupt
Transmission

432

More
segments?

442

Indicate
Success

440

End

BPC=0; NRC=0;
TC=0;
NACKcount=0

436

Frm timer=0
or TC>
Unit

Indicate frame
dropped

438

336

Wait for VCS=0
+ CS=0;
Update VCS,VPF
+ CC on
frame control

404

405

VPF=1

408

Signal
sensed in
CSS

410

CC=1?

416

Signal/Listen
in PRS

418

Heard
higher
priority?

419

Contention
for Channel

421

Valid
frame
control?

414

Set
VCS=EIFS,
VPF=0

422

Update VCS
VPF=1

412

Contention
or Interrupt
Transmission

419

Contention
for Channel

421

Valid
frame
control?

414

Set
VCS=EIFS,
VPF=0

422

Update VCS
VPF=1

FIG. 23

004080"6092E960




FIG. 24

From Step 418 (FIG. 23)




FIG. 25

004080"60922960

004030-080400




FIG. 27

575

004080"60922960




FIG. 28




FIG. 29

004030.6092960




FIG.

580




FIG. 31




FIG. 32




FIG. 33

09632609.080400

004030-6092E960




FIG. 34

09632609-080400

from FIG. 34

720




FIG. 35

09632509-080400




FIG. 36

700




FIG. 37

740

744	746	748	750	754	756	752	760	758
Connection Number	Master	SA	SA Frame Size	Min Frame Time	Max Frame Time	Tx Frame Size	Frame Life	Control


FIG. 39A

742

Connection Number	762
-------------------	-----

FIG. 39B

09632609.080400







FIG. 41

09632609 080400

98




FIG. 42




FIG. 43

838





FIG. 44

840



102




FIG. 46